



SAFETY RECALL NOTICE

RECALL CAMPAIGN # 12T-022

TO: Sailun Tire Dealers

Sailun Co. Ltd. has decided that a safety defect exists in certain Sailun S825 385/65R22.5 18PR 158K tires. Accordingly, a recall to address this issue is being initiated effective September 20, 2012.

The defect involves the possibility of inadequate liner gauge which could lead to reduced air retention over a period of time leading to the formation of separation and eventual tire failure.

The following 44 pcs – Sailun S825 385/65R22.5 18PR 158K tires fall under this recall.

Suspect Tire Bar Codes/Serial Numbers			
2143104663	2143203830	2143303664	2153102666
2143104762	2143203860	2143303670	2153102668
2143104764	2143203862	2143303674	2153204132
2143104768	2143203932	2143303884	2153204578
2143104770	2143203934	2143303886	2153303118
2143104846	2143203936	2143303888	2153303120
2143104850	2143203938	2143303894	2153303122
2143104852	2143303484	2153102656	2153303124
2143104856	2143303488	2153102658	2153303126
2143202482	2143303490	2153102662	2153305116
2143203828	2143303662	2153102664	2153305118

Date Codes for the above tires are “DOT 5371 SL 1312” & “DOT 5371 SL 1412”

Owners will be notified by mail about the recall and will be instructed to return their tires to the place of purchase to have them replaced with compliant tires at no charge. There is no cost to owners for this recall.

Sailun Co. Ltd. will provide you, our distributor/dealer, with compliant tires to exchange those under recall. Sailun Co. Ltd. will cover all costs incurred relative to this recall including labor and freight costs.

Please be reminded that it is a violation of Federal law for you to sell any of the noncompliant items covered by this notification until this recall has been performed on these tires. Substantial civil penalties apply to violations of this law.

Your assistance with this recall is appreciated. Should you have any questions or concerns, please contact Dirk DeBruin at DDebruin@Sailuntire.com or 905-595-3593